

Analysis of Available Drilling DataApr. 19/68Pine Creek - Gold Run:

- of the $3\frac{1}{2}$ miles Johnson includes in his reserves estimates only $\frac{1}{2}$ mile has been drilled - with 6 lines of holes 400' to 900' apart,
- 30 holes reached bedrock (3 others didn't)
- the 30 holes indicate an average grade of $32^{\circ}/\text{cu.yd}$ over an av. $35'$ vert. interval. (this contrasts with Johnson's estimate of $70^{\circ}/\text{cu.yd}$ over $51'$ av. depth.)

Otter Creek:

- ~~**~~ the approx 3 miles Johnson includes in his reserves estimates have only been tested by 5 lines of holes ; the upper 2 lines are 2 miles apart.
- the 5 lines have 37 holes ; those 34 holes indicate an avg. grade of $38^{\circ}/\text{cu.yd}$ over an av. $70'$ vert. interval (this contrasts with Johnson's overall estimate of $45^{\circ}/\text{cu.yd}$ over an $85'$ av. interval.)

Apr 18/68

- upper 2 miles of "Gold Run" ~~probably~~ possibly buried beneath soft limestone wall of Pine Creek.
This is indicated by 1) indicated ~~the~~ ^{the indicated} marked southward bedrock fall on the KE line & 2) indicated southward bedrock fall on L line.
3) indicated southward improvement in values of KE + ~~L line~~ possibly ^{and} the L lines.
- the bank must be getting steep, i.e. the good No. 3 hole on line KE is above the ditch & all the holes on line L are ~~above~~ the ditch.
- probably great difficulty in manoeuvring a very large dredge up Otter Creek
- he spoke of considerable large boulders on Weigle Creek - very likely the same conditions on Otter Creek.
- 1966 report spoke of difficulty of clay-cemented gravel on Pine Creek.
- all place operators undoubtedly know of this situation & have declined to pursue it.
- no likelihood of any significant additional resources.
- to get drilling organized quickly would require direct involvement of the Johnsons