

N.J. Stan  
C.C.STANDARD

February 29, 1948.

DEVELOPMENT RECOMMENDED

"A" - To be done as soon as possible.

"B" - To be done later.

"C" - To be done last.

LEVEL 6Distance

<u>620</u>			
"C"	Continue main drift East on vein a minimum of 40', or more if vein opens up.		40'
"A"	Drift East on vein in "cut off" x-cut to fault		30'
"A"	Raise on vein from at or near 620 x-cut		25'
"B"	Continue main 620 Raise as far as ore extends		50' ?

<u>619</u>			
"C"	Later, prospect Eastward along old drift, from present face.		60'

633 Region

"A"	Drift West on ore (Elev. 1473) as far as it extends		?
"A"	Drift West 10' in 631 to open ore at Co-ord. (1180 N - 1150 E.)	Elev. 1456,	10'
"A"	And raise to ore at Elev. 1473 if then advisable		35'
"B"	Raise from Drift at Elev. 1473 as far as ore extends		?
"B"	Work upward in N.W. of old Stopes later as developments indicate, perhaps through drift and raise (1260 N. - 1145 E.) at El. 1467		?

<u>640</u>			
"A"	Continue drift E. on vein across old Raise as far as ore extends		?
"A"	Continue raising (and stoping) all along back where in ore.		?
"C"	Explore vein-split floors 4, 5, & 6 at Co-ord. 1400 N. by slashing, and if results favorable x-cut for it on sill.		?

<u>640 - 660 Fault Zone</u>			
"B"	Drift southerly in F.W. of fault from 640 x-cut in Quartz and Zinc (?), as per D.D. Hole #138		30'

<u>650</u>			
"B"	Continue Raise near end W. Drift to 501 Sill		30'
"C"	Continue W. Drift or if runs out of ore x-cut to Right		35' ?
"A"	In Raise 20' E. of main x-cut slash 10' S.E. at top to ore in D.H. and follow upward		50'

<u>624</u>			
"B"	Raise along E. end of old 624 Stopes, on ore		40'

<u>601 Inter. at Elev. 1494</u>			
"B"	Continue Drift from (1525 N - 1445 E.) face to ore in D.D. Hole #11 (13% Zinc sludge) at Elev. 1506. Driving S 85° W.		75

LEVEL 5.

"A"	Prospect area from 5 Level "I" vein to "A" intermediate and 525 Intermediate through present workings.		0
"C"	Break into "A" intermediate from old Raise at (1215 N. - 1440 E.) through new Raise about 15 ft. <i>then</i>		15'

<u>520 Raise</u>			
"B"	Re-open old drift w. on old Intermediate and watch for vein turning off to Right.		50'

<u>10' E. of 503 Raise</u>			
"B"	X-cut to ore in N.W. (10 ft.) and raise on it.		?

<u>506 Raise - "I" Vein or Spur</u>			
"A"	Continue about 15 ft. to ore in drill hole and if OK continue Raise.		50' ?

STANDARDDEVELOPMENT RECOMMENDED

February 29, 1948.

LEVEL 5 (Cont'd)505 Stone

"p" Raise from 5 Level at 70 ft. West of 505 Raise (prospecting and ore pass) (Vertical through F.W. gouge then up along it) 70°

503

"p" Open area over 503 Raise from East end 501 9th floor or present Raise in z-cut from (Preliminary work, mostly timbering)

No development planned on #3 and #4 levels for present.

---

Compiled with the assistance and approval of R. T. Avison.

*Char. C. Starr*  
\*\*\*\*\*  
C. C. Starr, Geologist.