

92H/16E

881372

BRENDA

Wed. July 26/00

92H NE 047

photo - look N over pit (bottom)

photo - look S " "

- walk along bench (above
~700 ft. deep water)

- very 'homogeneous' - very little
dyking (apite/bstt)

- looks like good grade control

- Moly treatment plant built to
treat at least 100 yds of
water filling up pit.

Sludge from pit + tailings
water treatment = 43% Fe; 7% Mo