



MILL  
↓

2882  
Bench

Wedge Failure  
↓

DENAK  
PITS

44. Looking south only over  
main zone pit, ENDAKO

CUSTOM CLRL150813 0122 N-1 1-12

882720

CUSTOM CLRL120813 0122 N-1 1-12

CUSTOM CLRL150813 0122 N-1 1-12

CUSTOM CLRL090813 0122 N-1 1-12

CUSTOM CLRL050813 0122 N-1 1-12

CUSTOM CLRL050813 0122 N-1 1-12

