
A Zone Level 5100 5800
5900
5800
5400
5300
5070
5200
5600
5130
15 00
"C" ZONE
"B" ZONE
"A" ZONE
X-FAULT ZONE
SHOP
CRUSHER ROOM
MILL ROOM
EST^D CAVE
EST^D OUTLINE OF CAVE
EST^D STOPE OUTLINE
COLOUR CODE
"A" ORE
"B" ORE
"C" ORE
"X" FAULT ORE
61629
March 1964
COWICHAN COPPER CO.
750676
SUNRO MINE
LEVEL PLANS SCALE 1"=40'
14