093 P/4

BRAMEDA RESOURCES LTD.

SUKUNKA COAL TESTING

SEAM: CHAMBERLAIN SEAM

810782

HOLE NO.	SAMPLE NO.	FROM	TO	WIDTH FT.	REC. FT.	TOTAL MOISTURE	SURFACE MOISTURE	INHERENT MOISTURE	ASH%	VOLATILE	FIXED CARBON	B.T.U. AIR DRY	SULPHUR %	F.S.I.	[illegible]
S-1	S-012	432.0	437.1	5.1	4.5	3.24	2.57	0.70	3.45	25.05	70.80	15,220	0.38	8.0	
S-2	(a)	100.7	129.5	28.8	14.0)	Analysed	-	0.90	7.40	25.90	65.80	14,300	0.34	3.5	
	(b)	100.7	129.5	28.8	14.0)	in Japan	-	1.12	7.90	24.02	66.96	14,800	0.57	8.0	
S-4	S-041	54.0	63.2	9.2	6.5	1.83	1.29	0.55	8.65	22.78	68.02	14,546	0.48	5.0	
S-5	S-052	512.7	521.8	9.1	8.0	3.16	2.70	0.47	6.90	19.66	72.97	14,970	0.64	6.0	
S-8	S-081	141.5	146.1	4.6	4.6	2.92	2.17	0.77	3.50	24.28	71.45	15,095	0.52	7.5	6.[illegible]
S-11	S-11-2	275.0	283.0	8.0	6.0	1.48	1.11	0.37	6.85	24.13	69.65	14,870	0.47	6.5	
S-12	S-12-1	444.5	453.0	8.5	8.5	1.92	1.53	0.40	4.95	23.45	71.20	15,269	0.46	8.5	13.0
S-13	S-13-1	369.5	381.0	11.5	11.5	1.64	1.13	0.52	5.65	24.23	69.60	15,170	0.47	7.5	26.5
S-14	S-14-1	246.0	257.0	11.0	6.0	3.44	3.00	0.45	8.0	24.80	66.75	14,696	0.52	7.0	[illegible]
S-15	S-15-1	229.0	237.5	8.5	8.0	1.92	1.50	0.43	6.55	22.25	70.77	14,970	0.45	7.0	9.[illegible]
S-16	B-16-1	1258.0	1273.0 ?	10 +	- 4.0	1.50 Core	Broken	0.78	10.33	21.40	67.49	13,736	0.33	6	3.3[illegible]
S-17	A-17-1	276.0	283.0	7.0	7.0	0.89		0.89	4.68	25.25	69.18	14,663	0.34	8.5	9.52[illegible]
S-18	A-18-1	282.5	292.0	9.5	9.5	0.93		0.75	4.73	23.72	70.80	14,668	0.46	7.5	11.7[illegible]
S-19	A-19-2	157.0	162.5	5.0 +	5.0	1.51		0.74	3.68	25.78	69.80	14,896	0.52	9	1.[illegible]
S-20	A-20-1	1238.0	1246.0	8.0	4.5	1.88		0.58	6.85	24.70	67.87	14,334	0.50	6.5	3.0[illegible]
S-21	A-21-1	625.5	634.0	8.5	7.5	0.86		0.86	5.54	22.66	70.94	14,500	0.45	7	7.51[illegible]
S-22	A-22-1	708.5	716.2	7.7	7.7	1.48		0.82	6.14	22.98	70.06	14,504	0.58	9	11.0[illegible]
S-23						Chamberlain Seam Cut out by Fault?									
S-24	A-24-1	909.5	918.0	8.5	8.5	1.13		0.99	4.47	23.06	71.48	14,759	0.37	8	6.1[illegible]
S-25	A-25-1	1474.0	1482.5	8.5	8.5	0.87		0.74	4.11	24.04	71.11	14,845	0.35	8.5	5.00
S-26		1369.5	1377.5	8.0	8.0										

COAST ELDRIDGE

COMMERCIAL TESTING & ENGINEERING

BRAMEDA RESOURCES LTD.

SUKUNKA COAL TESTING

* Shale partings included - analyses by Coast Eldridge. Other samples, shale partings over 1" omitted, analysed by C-T & E

SEAM: SKEETER SEAM (Upper Chamberlain)

HOLE NO.	SAMPLE NO.	FROM	TO	WIDTH FT.	REC. FT.	TOTAL MOISTURE	SURFACE MOISTURE	INHERENT MOISTURE	ASH%	VOLATILE	FIXED CARBON	B.T.U. AIR DRY	SULPHUR %	F.S.I	WHI...
S-1 *	S-011	405	412.5	7.5	5.0	0.55 *			6.40	24.55	68.50	14,920	0.42	8.5	
S-19	A-19-3	133.3	142.0	8.7	6.3	0.87			12.89	21.85	64.39	13,330	0.45	7.0	7.3
S-18	A-18-2	258.3	263.6	5.3	4.9	0.65			7.30	23.33	68.72	14,250	0.42	8.0	5.3
S-17	A-17-2	245.2	252.6	7.4	2.7	0.97			12.57	19.75	66.71	13,369	0.61	7.0	3.3
S-24	A-24-2	868.2	877.5	9.3	9.3	0.79			8.06	22.75	68.40	14,170	.46	8.0	4.3
S-21	A-21-2	593.8	602.0	8.2	6.8	0.83			9.83	23.11	66.23	13,838	.45	7.0	9.5

BRAMEDA RESOURCES LTD.

SUKUNKA COAL TESTING

SEAM: COMMOTION SEAM "A"

Stratigraphic Position is approximately 1203 ft. above Chamberlain Seam

HOLE NO.	SAMPLE NO.	FROM	TO	WIDTH FT.	REC. FT.	TOTAL MOISTURE	SURFACE MOISTURE	INHERENT MOISTURE	ASH%	VOLATILE	FIXED CARBON	B.T.U. AIR DRY	SULPHUR %	F.S.I	[illegible]
S-23	#327	36.0	45.5	9.5	8.0			1.18	21.56	23.45	53.81	11,619	0.35	4.0	6.6[illegible]
S-27	326	5S.0	64.0	6.0	5.7			0.97	16.86	24.85	57.32	12,275	0.35	5.5	6.9[illegible]