

# Bethlehem Copper

**C O R P O R A T I O N L T D N P L**

P.O. BOX 520  
ASHCROFT. B.C.

October 14, 1964.

Dr. J. M. Carr,  
Dept. of Mines & Petroleum Resources,  
Victoria, B. C.

Dear Mike:

Enclosed are:

- (1) Copper and Moly assays for the following benches  
4840, 4810, 4780, 4750, and 4720. ✓
- ✓ (2) Assay plan 4840 bench.
- ✓ (3) Fault pattern in the 4840 bench.
- ✓ (4) Vertical section 11000N (East Jersey)
- ✓ (5) Vertical section 11400N (East Jersey)
- ✓ (6) Vertical section 11700N (East Jersey)
- ✓ (7) Vertical section 3729E (Huestis Zone)
- ✓ (8) Vertical section 9000N (Iona Zone)
- ✓ (9) Vertical section 11700N (Jersey)
- ✓ (10) Moly flow sheet.
- ✓ (11) Moly assay from various diamond drill holes in the  
different ore zones.
- ✓ (12) Summary of item #11.
- ✓ (13) Plan of Huestis drilling

Yours very truly,

BETHLEHEM COPPER CORPORATION LTD. N.P.L.



C. J. Coveney,  
Production Engineer.

CJC/tb  
Enc.

*All in Rm 429*  
*[Handwritten initials]*