

020416

82E5E266

GREENWOOD SLAG ASSAYS.
Monthly Averages.

		Cu	SiO2	Fe	CaO	Aug	Ag
Aug. 1914		.298	35.2	21.	42.3	.004	.048
Mar. 1914		.247	42.7	18.7	22.5	.005	.083
Aug. 1913	#1 furnace	.245	44.2	14.7	26.9	.003	.061
	#2 "	.278	44.1	14.4	26.5	.003	.063
Mar. 1913	#1	.3	42.	16.8	25.6	.003	.048
	#2 "	.31	42.	16.7	25.5	.003	.05
	#3	.31	42.1	16.9	25.4	.004	.055
Aug. 1912	#1 "	.265	44.	16.6	24.3	.003	.034
	#2	.267	44	16.6	24.2	.003	.036
	#3	.269	43.8	16.9	24.1	.003	.034
Mar. 1912	#1	.294	43.7	16.8	26	.004	.040
	#2	.282	43	17.8	25.4	.004	.067
	#3	.281	42.9	17.7	25.21	.005	.042
Aug. 1911	#1	.249	43.5	17.5	23.8	.006	.053
	#2	.2565	43.4	17.7	23.5	.006	.051
	#3	.236	43.7	17.2	23.6	.006	.047
Mar. 1911	#1	.253	43.1	17.5	23.5	.0035	.057
	#2	.292	42.8	18	23.5	.003	.083
	#3	.268	43.3	17.65	23.5	.0035	.064
Aug. 1910	#1	.2735	43.2	17.8	23.5	.004	.057
	#2	.274	42.8	17.5	24.3		
	#3	.264	42.9	18.1	23.6	.004	.058
Mar. 1910	#1	.322	39.09	19.96	24.9	.003	.032
	#2	.327	39.02	20.1	24.82	.004	.036
	#3	.321	39.16	20.02	25.	.004	.038
Aug. 1909	#1	.333	41.77	18.55	24.51		
	#2	.333	41.66	18.51	24.58		
Mar. 1909	#1	.335	39.4	19.5	24.6		
	#2	.337	39.3	19.3	24.8		
Aug. 1908	#1	.38.	38.8	20.4	24.4		
	#2	.36	38.7	20.4	24.4		
	#3	.36	38.7	20.1	24.8		
Aug. 1907	#1	.38	40.3	20.1	23.2		
	#2	.38	40.4	19.9	23.1		
	#3	.36	39.9	20.2	23.3		
Mar. 1907	#1	.442	38.26	22.63	21.66		
	#2	.415	38.17	22.6	21.9		
May 1906	#1	.331	43.18	19.78	21.03		
	#2	.335	43.6	20.64	21.21		