

DDH Signs* Doug's holes✓ Single Signs

	<u>DDH</u>	<u>Azm</u>	<u>Incl.</u>
✓	* 86R-116	205°	-45°
✓	* 86R-118	205°	-56°
✓	* 86R-119	205°	-45°
✓	* 86R-121	205°	-45°
✓	86-122	203°	-51°
✓	86-123	203°	-51°
✓	86-124	203°	-51°
do	86-125	203°	-52°
✓	86-126	203°	-52°
✓	* 86R-127	203°	-45°
✓	* 86R-128	203°	-45°
do	86-129	203°	-66.5°
✓	* 86R-130	203°	-45°
do	86-131	203°	-50°
	86-131	203°	-50°
do	86-132	203°	-45°
✓	86-133	28°	-80°
✓	86-134	28°	-80°

DDH
86 - 135

Azm 28° Incl -80°

86 - 136

208 -47.5°

* 86R - 137

(obtain from AOM or from chart)

II Double Signs

DDH
86 - 129

Azm 208° , Incl -66.5°

~~86 - 131~~

~~208 $^{\circ}$, -50 $^{\circ}$~~

86 - 138

208 $^{\circ}$, -65 $^{\circ}$

86 - 139

208 $^{\circ}$, -45 $^{\circ}$

86 - 140

208 -51°

86 - 141

~~28 $^{\circ}$, -80 $^{\circ}$~~

86 - 142

208 $^{\circ}$, -63 $^{\circ}$

1 86 - 143

192 $^{\circ}$ -55°

1 86 - 144

208 -46°

86 - 145

192 -56°

86 - 146

192 -47.46°

86 - 147

208 $-46\frac{1}{2}$



