

92F/2E

PROPERTY FILE

92F-82



LEGEND

Stoped areas


Stripping

Vein, showing dip

Fault, showing dip



NORTH



Permission to publish this has not been granted; however a full description of the workings has been added to the report.
J.H.
Apr 11/37.

Albani

300

250

007037

See 1936 Report
Tangerine Island Gold Mines Ltd.
4100x 928T