
TRENCH AREA NOT MAPPED
ROAD GEOLOGY NOT MAPPED
RCH-14
RCH-15
RCH-13
RCH-10
RCH-11
RCH-9
WG
WH
WE
WF
WA
WB
WC
WD
E.Rd.Pt.
SW Pt.
SS 3-79
IS IT POSSIBLE THE GOLD ZONE IN RCH-11 IS PART OF THIS ALTERATION ZONE?
SEQUENCE IN DIKE AREA VERTICAL SECTION
GRANITE
THE STRUCTURE APPEARS TO BE OFFSET (EAST SIDE NORTH) ON SEVERAL NORTH TRENDING FAULTS, VEINS COULD BE LOCATED FOR NORTH OR SOUTH SIDE OF DIKE COMPLEX.
J.C. STEPHEN EXPLORATIONS LTD.
SIWASH SILVER PROJECT
SIMILKAMEEN M.D.
WESTERN TRENCH ZONE
GEOLOGY
673649
0 5 10 15 20
meters
MAP IV