
UNION MINE
LEVEL NO 3
SCALE 1 IN = 20 FT.
FAULT BLOCK "A"
FAULT BLOCK "B"
Union Fault
Maple Leaf Fault
480 N
560 N
103
S
T
U
R
A
D
E
Hard highly altered rock. Probably argillite absorbed into andesite sills
Andesite dike
Sandstone - hard black and fractured
Calcite seams
Little calcite
Grey dike
Tuff
Cal. Tuff
Tuff argillite
Tuffaceous Cal. Tuff
Cal. Tuff
Zacate dike
Tuffaceous Cal. Tuff
Tuffaceous Cal. Tuff
Tuffaceous Cal. Tuff