


DEPARTMENT OF NATIONAL DEFENCE
ARMY SURVEY ESTABLISHMENT

First Edition

93 J/1 WEST



GENERAL:

Drill Hole No. 1001 drilled by Boyles Bros Ltd. - February, 1958
Method: - wash-boring
Analysis: - Ripley & Associates, Vancouver

Drill Holes Nos. 1 to 10 drilled by Provincial Dept of Highways - January, 1958
Method: - mobile auger
Analysis: - Dept. of Highways, Soils Laboratory.


For Logs of Holes 1 to 10
- see accompanying sheets from Dept. of Highways.

93 J/1 WEST

93J/w

REFERENCE

Roads: more than a lane	Boundary, International	House, Building	Lighthouse
hard surface, all weather	Province	School	Wharf or Pier
hard surface, all weather	County or District	Church	Foreshore Flats
loose surface, all weather	Township or Parish	Post Office	Swamp or Marsh
less than a lane	City or Town	Tower, Radio Mast, Lighthouse	Lake or Pond, permanent
Can Track, Trail	Reservation, Indian, Military, etc	Cemetery	Lake or Snowfield
Railways: normal gauge, multiple track	Power Transmission Line	Quarry	Stream, intermittent
normal gauge, single track	Telephone or Telegraph, track route	Sand or Gravel Pit	Irrigation Canal, Ditches
abandoned, or under construction	Horizontal Control Point	Cliff	Inundated Land, seasonal
normal gauge, single track	Boundary Marker	Quarry	Canons, stream
Bridge, wooden or masonry	Bench Mark	Embankment	Woods, unclassified
Tunnel	Spot Elevation, (in feet)	Dry River Bed	Scrub
	Min or Pit		



REFERENCE

House, Building	Lighthouse
School	Wharf or Pier
Church	Foreshore Flats
Post Office	Swamp or Marsh
Tower, Radio Mast, Lighthouse	Lake or Pond, permanent
Cemetery	Lake or Snowfield
Quarry	Stream, intermittent
Sand or Gravel Pit	Irrigation Canal, Ditches
Cliff	Inundated Land, seasonal
Quarry	Canons, stream
Embankment	Woods, unclassified
Dry River Bed	Scrub

PROPERTY FILE
93J009-06