

841409
wayside

DDH 85-4
1:500
270°, -45°

W

75

50

25

0

E

NO OUTCROP

85-4
ROAD

716.5m

5.41

6.80

Chert with clay gouge on fractures

OVERBURDEN

ARGILLITE

21.80

Chert with argillite to 100%

26.82

altered argillite: epidote, chlorite + limonite

ARGILLITE

CHERT: with 1% argillite stringers

NO SAMPLES TAKEN



PUT THIS ABOVE
INFO. BOX IN
LOWER RIGHT
CORNER